

CORNER RECORD

COUNTY OF MADERA T. 7 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT MAY 1989



N 1/4 SECTION 26 7/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 METHODS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include)

① N 1/4 CORNER SECTION 26 7/19
RE-ESTABLISHED CORNER POSITION AT RECORD BEARING AND DISTANCE FROM ORIGINAL BEARING TREE.
SET REBAR AND CAP, UP 9", NO ROCK MOUND
ORIGINAL BEARING TREES:
 1. A 24" DIA. WHITE OAK WITH SCRIBING BEARS N.18 00'W. 72.6'
(N.18°W. 72.6')
 2. A 2" DIA. WHITE OAK PREVIOUSLY FORKED BEARS S.7 1/4°E
59.7' (S.11°E. 57.4')
NEW TIES
 3. A 7 1/2" DIA. FORKED WHITE OAK BEARS S.33 W. 20.27' ALL
MEASUREMENTS TO NEAREST FORK
 4. A 30" DIA. WHITE OAK BEARS N.87°E. 32.17'
CORNER LIES 70' S. OF FENCELINE RUNNING NE'LY AND SW'LY

COPIED FROM R.S. BY SEIB-LS. 5509 36/45-46

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT

ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET