


CORNER RECORD

COUNTY OF MADERA T. 7 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT MAY 1989



W 1/4 SECTION 26 7/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
METHODS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

② W 1/4 CORNER SECTION 26 7/19

SKETCH: (Include)

FOUND A 1 1/2' DIA. X 1/2' HIGH ROCK MOUND WITH POST REMAINS IN THE CENTER. REMONUMENTED WITH A REBAR AND CAP, UP 6" REBUILT ROCK MOUND 2 1/2" DIA X 1' HIGH AROUND MONUMENT. ORIGINAL BEARING TREE

1. A 19.5 DIA WHITE OAK WITH SCRIBING BEARS N.27 3/4° E. 76.3' (N.39 1/2° E. 75.2')

NEW TIES

2. A NAIL IN A 6' X 3 1/2' X 1' HIGH ROCK BEARS N.19°31'05"E. 4.94'

3. A NAIL IN A 2 1/2' X 1 1/2' X 1 1/2' HIGH ROCK BEARS N.61°41'51"E. 49.92'

FOUND A 1" IRON PIPE, UP 6", NO TAG S.47 25'28"E. 43.81' FROM THE CORNER — NOT ACCEPTED FOUND PIPE LIES 9" E. OF FENCELINE RUNNING N'LY AND S'LY.

COPIED FROM R.S. BY SEIB-LS. 5509 36/45-46

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No.: _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET