


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MADERA, California

Brief Legal Description \_\_\_\_\_



### CORNER TYPE

- |                   |                          |          |                          |
|-------------------|--------------------------|----------|--------------------------|
| Government Corner | <input type="checkbox"/> | Control  | <input type="checkbox"/> |
| Meander           | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho            | <input type="checkbox"/> | Other    | <input type="checkbox"/> |
| Date of Survey    | <u>SEPT. 17, 1995</u>    |          |                          |

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

*NORTH 1/4 CORNER, SECTION 27 7/10  
 PD (1) B.T. SET 3/8" REBAR L & S 5509 UP 4"  
 W/ FENCE POST FROM WHICH BEARS:  
 W. OAK 5.78° E. 15.7  
 CHISELED "X" IN 6x3x2" HIGH ROCK N. 9° E. 42.25  
 CHISELED "X" IN 7x2x3" HIGH ROCK S. 74° W. 42.41  
 7" W/ OAK W/ JACK MARK S. 64° E. 31.10*

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment COPIED FROM JONES & SNYDER  
RECORD OF SURVEY, RECORDED IN BOOK 44 OF MAPS  
AT PAGE 145