


CORNER RECORD

MARIPOSA

COUNTY OF _____ TOWNSHIP 7 SOUTH, RANGE 19 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: APRIL 19 73



WEST 1/4 CORNER OF SECTION 31, 7/19.

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT


PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found BLM brass cap monument.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)



Copied from Record of Survey of Buchanan Dam Boundary
Surveyed by James E. McPheeters, L.S. 2854

21/86-92

SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19 _____.
SIGNED: _____
L.S. or R.C.E. No: _____
SEAL

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19 _____.
AND EXAMINED AND FILED _____ 19 _____.
BY: _____
TITLE: _____
DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES NO