


**CORNER RECORD**

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of \_\_\_\_\_, California

Brief Legal Description SECTION 5 T 7 S RANGE 20 E



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone  NAD27  NAVD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum:  NGVD29  NAVD88   
Meas. Units:  Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

PER RECORDED SURVEY FOR JACKSON IN BOOK 56  
PAGE 18

A description of the physical condition of the monument as found and as set or reset:

SET A NAIL TAG LS 5339¢  
TIN SET IN THE FACE OF A 7" BLUE OAK BEAMS S60° E 9.0

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

The Land Surveyor's Act on \_\_\_\_\_

Signed \_\_\_\_\_ P.L.S. or R.C.E. No. \_\_\_\_\_

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received \_\_\_\_\_

and examined and filed \_\_\_\_\_

Signed \_\_\_\_\_ P.L.S. or R.C.E. No. \_\_\_\_\_

Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_