


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 7 SOUTH, RANGE 20 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



NORTHWEST CORNER SECTION 9 7/20

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 17" X 15" X 11" SET STONE

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

RESET 2" I.D.I.P. TAG L.S. 4509 IN CAIRN UP 0.30'

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

| | | | |
|---------|--------|------|---|
| S 42° W | 31.11' | TO A | 22" BLUE OAK SET K TAG |
| N 54° W | 24.26' | TO A | N & T IN A 8'x20'x8' GRANITE OUTCROP |
| NORTH | 0.90' | TO A | FENCE TO WEST |
| EAST | 0.30' | TO A | NORTH-SOUTH # FENCE |

COPIED FROM R/S FOR BRUDER BY BREADAHL L.S. 4509 *RS 27/179*

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES NO