


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 7 SOUTH, RANGE 20 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19 ____



NORTHWEST CORNER SECTION 11 7/20

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 1 1/2" IRON PIPE UP 2" IN SMALL ROCK MOUND

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

S 77° E	72.60'	OF	24" WHITE OAK BLAZE
N 75° E	156.10'	OF	30" STUMP
S 28° W	8.00'	OF	10" WHITE OAK SET BLAZE
WEST	3.60'	OF	FENCE N & S
SOUTH	7.00'	OF	FENCE WEST

COPIED FROM P.M. # 1918 BY GREENWOOD RCE 12406

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19 ____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 ____

AND EXAMINED AND FILED _____ 19 ____.

BY: _____

TITLE: _____

DOCUMENT No: _____

STATEMENT ON BACK OF SHEET: YES NO