

CORNER RECORD

COUNTY OF MADERA TOWNSHIP 7 SOUTH, RANGE 20 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: DECEMBER 19 74



SOUTHWEST CORNER OF SECTION 36, 7/20.

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 2" Iron Pipe with GLO Brass Cap in rock mound, 8" up.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION STATION
ZONE ELEVATION NORTHINGS (Y) EASTINGS (X)

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES

25.20 feet S.W. of a shiner in a 14" White Oak.

30.90 feet WEST of a shiner in a 12" White Oak.

14.85 feet NORTH of a shiner in fence post.

Copied from Parcel Map 897
Surveyed by R. W. Greenwood, RCE 12406

20/89

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 19 AND EXAMINED AND FILED 19

BY: _____

TITLE: _____

DOCUMENT No: STATEMENT ON BACK OF SHEET: YES [] NO []