


CORNER RECORD

Document Number FROM RS. BK. 44 PG. 8

City of _____

County of MADERA, California

Brief Legal Description N.W. CORNER SECTION 1, TOWNSHIP 7 SOUTH, RANGE 21 EAST
MDBM



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|--------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |
| Date of Survey | <u>AUGUST 1994</u> | | |

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REDWOOD POST # 2" B. CAP L.S. 4261 IN PLACE.

A description of the physical condition of the monument as found and as set or reset: _____

TIES:
1. S20W, 23.50, NAIL IN 6" MANZANITA
2. N18E, 45, S.W. HOUSE
3. N64W, 65.44 TO PK. IN ROCK OUTCROP

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment _____

