


CORNER RECORD

COUNTY OF Madera T. 7 S. R. 22 E. M.D.B. & M. MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT March 26 1984



The east 1/4 corner of section 6 7/22.
(common to section 6 only)

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found and Accepted: A 1" O.D. iron pipe, up 11", with a 2 1/2" dia. GLO brass cap stamped for the corner, the date and the GLO logo per field notes of A.W. Brown, U.S. Deputy Surveyor, 1917.

PHYSICAL DESCRIPTION OF MONUMENTS RESULT OR PERPETUATED

Left the monument as found.
Set a metal post with Forest Service monument signs attached, 4' ± NE of the monument.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

Corner Ties: (Basis of Bearings is magnetic, dec.=16 1/2° E)

Cap Inscription

1. A Ponderosa Pine, 20" dia. bears N 61° 42' W, 24.05'.
2. A Ponderosa Pine, 26" dia., bears N 40° 48' W, 45.05'.
3. A Ponderosa Pine, 5" dia., bears S 19° 18' W, 33.02'.

1/4
S 6
1917

The W 1/4 corner of section 5 bears N 1° 06' 24" E 171.42'.
The corner lies 6' ± north of a drainage.

C-5
F.B. 25/69 & 24/29
Job No. 84-01
(Continued on back)

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS REPAIRED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYING ACT ON _____

SIGNED: Harold Donald Cohen

L.S. or REC. No. LS 4689

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 1986
AND EXAMINED AND FILED _____ 10/12/86
BY: [Signature]
TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET YES NO

Bearings are to the center of trees at the base. Distances are horizontal to a nail and tag (stamped LS 4689) driven into the side center of the root crown.

Posted Forest Service monument signs.

0822 250640

