| CO | D1 | N | F | D | D | ς. | \cap | D | n |
|----|----|---|---|----|---|----|--------|---|---|
| - | | | _ | r. | п | _ | _ | ĸ | u |

| SUNTY OF MADERA T. 7 | 22 | _ MERIDIAN CALIFORNIA |
|---|--|---|
| CORNER TYPE: GOVT. CORNER MEANDER RANCHO | CONTROL OTHER 1 | • |
| W/4 Sec. 6 7/22 | | |
| CORNER — LEFT AS FOUND FOUND AND TAGGED RE | ESTABLISHED OBLITERATED CORNER [| REBUILT [|
| 3/4" 1.P. RCE 21650 | USED TO IDENTIFY OR REESTABLISH | |
| | | |
| PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED | | |
| | | |
| | 10 | |
| | | |
| | | |
| ZONE ELEVATION NORTHINGS () | OTHER STATION EASTINGS | STATION |
| | *************************************** | |
| SKETCH: (Include reference tie or witness points, remarks and topo | of area) | |
| TES: 1) IN FENCE LINE N/S | | |
| 2) Y. PINE 16" N65E, 23.1 | | |
| 3) MOUND OF STONE 2 FOOT AT ON W/S OF CORNER. | BASE ! 1/2 High, | |
| Copied From PM 290 | 06 36/6 | |
| SURVEYOR'S CERTIFICATE THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON | COUNTY SURVEY THE CORNER RECORD WAS RECEI AND EXAMINED AND FILED BY TITLE; DOCUMENT No | 19 |
| 100 | STATEMENT ON BACK OF SHEET | 7 - 17 Marcon 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 |
| SEAL | . ON BACK OF SHEET | YES NO |