


CORNER RECORD

COUNTY OF MADERA T. 7 S. R. 22 E. NDBE MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION - DATE OF VISIT Aug 6 1975



E 1/4 CORNER

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT


PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

2" G.L.O. BRASS CAP IN 3/4" IRON PIPE

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



NAIL AND TAG R.C.E. 5982 IN TREES

L.O. = LIVE OAK



THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON August 26 No. 5982 1975

SIGNED: _____

R.C.E. No. 5982

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 28th of Aug 19 75 AND EXAMINED AND FILED Aug 29 1975

BY: Jim Bellan
 TITLE: Civil Engr Asst.

DOCUMENT No. 75-31-07

STATEMENT ON BACK OF SHEET

YES NO