


# CORNER RECORD

COUNTY OF MADERA T. 7 S. R. 22 E. M.D.B. & MERIDIAN CALIFORNIA  
 CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
 CORNER IDENTIFICATION - DATE OF VISIT Aug. 6 19 75



SW CORNER

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


**2" G.L.O. BRASS CAP IN 1 1/2" I.P.**

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_


SKETCH: (Include reference tie or witness points, remarks and topo of area)

**NAIL & TAG R.L.E. 5982, E. SIDE 5" L.O. N20° 30' W 25.64'**  
 " " " " " **So. SIDE 6" L.O. N 83° 55' E 34.84'**  
 " " " " " **N.E. SIDE 8" L.O. S 25° 05' E 49.03'**  
 " " " " " **S.E. SIDE 12" BULL PINE S 31° 50' W 31.07'**



L.O. = LIVE OAK

SURVEYOR'S CERTIFICATE  
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON August 26 19 75  
 SIGNED: [Signature]  
 License or R.C.E. No. 5982



COUNTY SURVEYOR'S CERTIFICATE  
 THE CORNER RECORD WAS RECEIVED Aug 28 19 75  
 AND EXAMINED AND FILED Aug 29 19 75  
 BY: [Signature]  
 TITLE: Chief Engr Asst  
 DOCUMENT No. 75-31-02  
 STATEMENT ON BACK OF SHEET

YES  NO