CORNER RECORD		
COUNTY OF Madera T. 7 S. 22 E. M.D.B. &	MERIDIAN CA	ALIFOI
CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER SOLUTION - DATE OF VISIT LATILIATY 4 1989		T. C.
The east 1/16 corner of section 8 7/22. (Common to sections 5 and 8)		
CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER		
CORRECT CORREC	REBUILT [
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISM The corner position was established by subdivision of section procedure.	ure.	
PHYSICAL DESCRIP "OF MONUMENTS REBUILT OR PERPETUATED		
Set F.S.M., flush. Set a metal post with Forest Service monument sign 4 1/2' +/- SW from the corner.	ns attached	
F.S.M Aluminum monument, 2 $1/2$ " O.D., 30" long with a 3 $1/4$ " O.D. stamped for the corner, with LS 5509, the date and the Forest Service	aluminum cap	
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD STATIONS USED: NGS (USC & CS) STATE COUNTY OTHER STATION ZONE ELEVATION NORTHINGS (7)	STATION	
SKETCH: (Include reference tie or witness points, remarks and topo of area)		
Corner Ties:	Cap Inscriptio	
1. A Ponderosa Pine, 10.5" dia., bears S 17° 00' W, 21.89'.		<u>111</u>
· •	S 5 1/16 S 8	
3. A Black Oak, 42.5" dia., bears N 49° 15' W, 98.94'.	LS 5509 1989	
nd a 1 1/4" O.D.I.P., up 10", no tag, S 64 ⁰ 27'04" W 5.86' NOT Acce	pted.	
corner lies 1/2' E'ly of a chain link fence (running N'ly and S'ly).		
rings are to the center of trees at the base. Distances are horizontation tag (stamped LS 5509) driven into the side-center of the root crown.	al to a nail	
ed and scribed bearing trees: "NBT".		
ed Forest Service monument and bearing tree signs ESSION E-8		
LAND STING F.B. 38/6 Job No. 8		
po-so.		
P. Control of the con	S CERTIFICATE	