


CORNER RECORD

COUNTY OF Madera T. 7 S R. 22 E M.D.B.& MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT 11-25- 19 74



West $\frac{1}{4}$ Corner Section 9

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


$2\frac{1}{2}$ " Brass Disc on 1" Iron Pipe set by U.S. General Land Office Survey 1917
 9" above ground.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 51.8' SE of Nail and Shiner in 48" Oak
- 54.7' NE of Nail and Shiner in 24" Pine
- 56.6' NE of Nail and Shiner in 18" Pine
- 65.3' NE of Nail and Shiner in 12" Pine
- 72.8' North of NW Corner of Block Wall
- 10' North of North Edge of Driveway to Willis



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 11-25- 19 74

SIGNED James W. H. [Signature]
 L.S. or R.C.E. No. 425 2924
 2924
 STATE OF CALIFORNIA
 SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED Dec. 2 19 74
 AND EXAMINED AND FILED Dec. 3 19 74

BY: Allent O. Grote
 TITLE: County Engineer
 DOCUMENT No. 74-31-1

STATEMENT ON BACK OF SHEET YES NO