CORNER RECORS)
COUNTY OF	MERIDIAN CALIF
CORNER TYPE: GOVT. CORNER MEANDER MEANDER MAY 14 CONTROL CONTROL	OTHER
The same of the sa	
15	
Northwest corner Section 15 7/22	
CORNER — LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OB	LITERATED CORNER [RESULT [
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY	PY OR REESTABLISH
RECORD: Post 4" square, 2' in earth, 2' above Field notes of W.F. Benson, U.S. Surveyor	June 1878
FOUND & Remains of original post with Roman Numer	
ACCEPTED side. Alongside the post was a 1 1/4" 0.	D. iron pipe with no tag
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED	
Set 30" long aluminum monument with a 3 1/4" alumin	
Forest Service logo, the date (1981), and LS 4689. from the monument with a Forest Service "Attention"	
From the mondment with a forest service meterician	Sign decached,
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER	STATIONSTATION
ZONE REPATION NORTHINGS (Y)	EASTINGS (X)
SKETCH: (Include reference tie or witness points, remarks and topo of area)	
CORNER TIES	CAP INSCRIPTION
N 41° 52' E, 54.94 Ft., to a 22" Incense Cedar	T7S R22E
S 44° 18' E, 33.27 Ft., to a 23.8" Incense Cedar	S 9 S 10 S 16 S 15
	LS 4689
S 38° 13' W, 55.16 Ft., to a 36.5" Ponderosa Pine	1981
N 75° 34' W, 45.99 Ft., to a 34.5" Black Oak (Origin	nal Rearing Tree)
N 75 54 W, 45,75 Pt., 20 a 54,5 Brack Oak (Origin	nai bearing free)
East, 34 Ft., to a creek	
General FO The company of the Compan	
South 53 Ft., to an E-W barbed wire fence	
Bearings are to the center of trees at base; distant	ces are horizontal to nail
and tag (stamped LS 4689) driven into base of trees	
Posted Forest Service Monument and Bearing Tree sign	ne
LAND S	10.
Blazed and arribed trees and stamped monument in acc	cord with Bureau of Land
HOWARD ARMOUT 13 "Manual of Surveying Instructions."	
COHEN	J - 13 1 25
SULVEY ATS CERTIFICATE	
222	COUNTY SURVETOR'S CERTIFICATE

STATEMENT ON BACK OF SHEET

DOCUMENT No.