


CORNER RECORD

COUNTY OF Madera T. 7S P. 22E MD MERIDIAN CALIF.

CORNER TYPE: GOV'T CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION --- DATE OF VISIT Sept. 1 1974



CORNER -- LEFT AS FOUND FOUND & TAGGED REESTABLISHED OBLITERATED CORNER
REBUILT


PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE & METHOD USED TO IDENTIFY OR REESTABLISH: Found 1" Iron pipe with GLO Brass Cap in rock mound dated 1917. Cap is erroneously stamped as 1/4 Cor between Sec. 17 & 18

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED:

Not Applicable

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NOS (USC & GS) STATE COUNTY OTHER STATION _____
STATION _____ ZONE _____ ELEVATION _____ NORTHINGS (Y) _____
EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)



- #1 28" Ponderosa Pine 7ft. N40W
- #2 29" Incense Cedar 56ft N89W
- #3 29" Canyon liveoak 22ft S76W

SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON Sept. 1 1974

SIGNED: [Signature]
L.S. of R.C.E. SIKORA AS 4126
NO. 4720
STATE OF CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED Sept. 5 1974
BY: Albert O. Krute
TITLE: County Engineer

DOCUMENT No. 74-16-1
STATEMENT ON BACK OF SHEET
YES NO