


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 7 SOUTH, RANGE 22 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



NORTHWEST CORNER SECTION 17 7/20

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND u.s.g.l.o. BRASS CAP WITH 4" IRON PIPE GAURD POST TAGGED R.C.E. 5982 IN FENCE LINE NORTH-SOUTH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

EAST 0.40' OF IRON PIPE UP 4.0' R.C.E. 5982
SOUTHWEST 47.30' OF 48"BLACK OAK, TWIN TRUNK
SOUTHEAST 56.00' OF 30" BLACK OAK
SOUTHEAST 61.75' OF 24" BLACK OAK

COPIED FROM RECORD OF SURVEY BY JONES 11-13-78

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____ STATEMENT ON BACK OF SHEET: YES [] NO []