


CORNER RECORD

COUNTY OF Madera T. 7 S. R. 22 E. M.D.B. & MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT July 1 19 82




Southeast - Northwest - Southwest 1/256 corner Section 21 7/22.
(NW corner of SE $\frac{1}{4}$ SE $\frac{1}{4}$ NW $\frac{1}{4}$ SW $\frac{1}{4}$ Section 21)

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Corner position established by section subdivision survey.



PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set: Standard FSM, up 5". Built a rock mound 1' at the base and $\frac{1}{2}$ ' high around the monument. Set a fiberglass post 4' \pm NW of monument with a Forest Service monument sign attached.
FSM - Aluminum monument, 2 $\frac{1}{2}$ " O.D., 30" long with a 3 $\frac{1}{4}$ " O.D. aluminum cap; stamped for the corner, with L.S. 4689, the date, and a Forest Service logo.

CALIFORNIA COORDINATE SYSTEM ORDER FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

KETCH: (Include reference tie or witness points, remarks and topo of area)

CORNER TIES:

- | | |
|--|---|
| <p>Centerline of a 15' \pm wide paved road, bears North, 45'.
A incense cedar, 7.3" dia., bears N 60° 48' E, 40.80'.
A P.K. nail & shiner in centerline of 15' \pm paved road (which bears S 40° E), bears N 88° 29' 12" E, 11.99'.
A ponderosa pine, 7.2" dia., bears S 27° 42' W, 93.83'.
A black oak, 16.0" dia., bears N 73° 08' W, 87.36'.
Centerline of 15' \pm paved road (which bears S 30° E), bears West, 33'.
Found 1" O.D., I.P., up 1" with plastic cap marked: Sikora L.S. 4126 (per parcel map No. 1208 MCCR) bears S 12° 59' W, 4.03'. NOT ACCEPTED.
Bearings are to the center of trees at the base. Distances are horizontal to a nail and tag (stamped L.S. 4689) driven into the side-center of the root crown.
Posted Forest Service Monument and Bearing Tree signs.
Blazed bearing trees.
Stamped monument in accordance with the BLM 1973 Manual of Surveying Instructions.</p> | <p><u>CAP INSCRIPTION</u></p> <p>S 21
SE-NW-SW
.
1/256
L.S. 4689
1982</p> |
|--|---|

P.75-9.75
1-66

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON October 13 19 82

SIGNED: Howard Arnold Cohen
L.S. or P.C.E. No. 4689

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED _____ 19 _____ BY: Howard Arnold Cohen TITLE County Surveyor

DOCUMENT No. _____
STATEMENT ON BACK OF SHEET