CORNER RECORD MERIDIAN CALIFORNIE CONTRACTOR GOVT. CORNER S MEANDER [тикно 🗆 OTHER [CONTROL | The northwest corner of section 29 7/22. (common to sections 19, 20, 29 and 30) CORNER -- LEFT AS FOUND TO POUND AND TAGGED REESTABLISHED OBLITERATED CORNER (REBUILT [PHYSICAL DESCRIPTION OF CORNER FOUNDS EVEDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH Found and Accepted: A GLO iron pipe, 1 5/8" O.D., with a 2 1/2" brass cap stamped for the corner, the date(1917) and the GLO logo. Found 4 bearing trees per field notes of A.W. Brown, U.S. Deputy Surveyor, 1917. PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED Left the monument as found. CAUFORNIA COORDINATE SYSTEM ORDER: FIRST 🔲 25€COHD □ THIRD | STATIONS USED: HGS (USC & GS) STATE [COUNTY [OTHER | STATION ELEVATION . EASTINGS IX SKETCH: (Include reference tie or witness points, remarks and topo of area) Corner Ties: Cap Inscription 1917 GLO Bearing Trees: T7S R22E S 19 1. A Yellow Pine, 34.4" dia., bears S 11° 52' W, 20.53'. S 30 S 29 (healed blaze) 1917 2. A Ponderosa Pine, 34.8" dia., bears N 58° 33' W, 16.03'. (healed blaze) 3. A Ponderosa Pine, 23.7" dia., bears N 30° 46' E, 29.26'. (healed blaze) 4. A Ponderosa Pine stump, 18" ± dia., bears S 33° 14' E, 19.4'. (no nail) New Bearing Objects: 5. A Live Cak, 27.9" dia., bears S 63° 21' E, 49.04'. R-5 F.B. 19/80 Mon. Bk. 2/69 Job No. 83-20 (Continued on back) THIS CORNER RECORD THE CORNER RECORD WAS RECEIVED DIRECTION IN CONFORM OHA OSHIMAKS OHA

LS 4589

OF CALIFORNIA

OF CALIFORNIA

TES

NO

TES

NO
TES

NO
TES

NO
TES

TES

TES

NO
TES

TES

TES

NO
TES

TES

SIGNED:

Fence lines run east, west and north from the corner.

A large pond lies 35' \pm south and 45' \pm west of the corner monument.

Bearings are to the center of trees at the base. Distances are horizontal to a nail and tag (stamped LS 4689) driven into the side center of the root crown, unless otherwise noted.

Posted Forest Service monument and bearing tree signs.