| CORNER RECORD | | | | | | |
|---------------|-----------|----------------|----------|-----|----------|--------|
| DERA | 1 | . 23 | mD |) B | MERIDIAN | CALIFO |
| CORNER [] | MEANDER S | RANCHO [] CONT | NOT OTHE | * 🗍 | | |
| w/4 | COP. | SEC. | 5 | | | |

REBUILT [

REESTABLISHED OBLITERATED CORNER

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND AND TAGGED [

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 3/4" IP. BRASS CAD LS. 4126

| | | | | | · · · · · · · · · · · · · · · · · · · | | |
|-------------------------------------|----------|--|----------|---------|---------------------------------------|---------|---|
| CALIFORNIA COORDINATE SYSTEM ORDER: | FIRST | SECOND (| | 🗀 оязнт | | | |
| STATIONS USED: NOS (USC & GS) [" | STATE [] | COUNTY [] | OTHER [] | STATION | | STATION | |
| ZONE ELEVATION | NO | RTHINGS (Y) | | | EASTINGS (X) | | · |
| | | The state of the s | | | | 4.4 | |

SKETCH: (Include reference tie or witness points, remarks and topo of area)

TIES :

COUNTY OF .

CORNER TYPE: GOVT. CORNER

CORNER - LEFT AS FOUND

CORNER IDENTIFICATION - DATE OF VISIT

10" INCENSE CEDAR NGE 18.1'
10" INCENSE CEDAR 558% 12.7'

| COPIED FROM ROF S HORRY | (SIKORA LS 4126) |
|--|--------------------------------|
| SURVEYOR'S CERTIFICATE | COUNTY SURVEYOR'S CERTIFICATE |
| THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY | THE CORNER RECORD WAS RECEIVED |
| DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT | AND EXAMINED AND FILED |
| ON | BY., |
| | Witte: |
| L.S. or R.C.E. No. | DOCUMENT No. |
| | STATEMENT ON BACK OF SHEET |