


CORNER RECORD

COUNTY OF MADERA T. 7 R. 23 M. D. B. & MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



Northwest corner Section 23 7/23

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT
 PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found Large Rock Mound & 4 Bearing Trees

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set Monument in Rock Mound

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (E) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

TIES:

- | | | |
|---------|--------|----------------------------|
| N 56° W | 19.65' | Original B.T. 5' Fir, Dead |
| N 36° W | 29.75' | New B.T. 8" S. Pine |
| N 64° E | 25.55' | Original 7' S. Pine |
| S 82° E | 34.7' | Original 6' Fir |
| S 28° W | 22.9' | Original 5' Fir |

All New Bearing Trees Blazed & Scribed

Copied from R/S for Bendix Forest Products by Jones L.S. 4298

<p align="center">SURVEYOR'S CERTIFICATE</p> <p>THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____.</p> <p>SIGNED: _____</p> <p>L.S. or R.C.E. No.: _____</p> <p align="center">SEAL</p>	<p align="center">COUNTY SURVEYOR'S CERTIFICATE</p> <p>THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____.</p> <p>BY: _____</p> <p>TITLE: _____</p> <p>DOCUMENT No. _____</p> <p>STATEMENT ON BACK OF SHEET YES <input type="checkbox"/> NO <input type="checkbox"/></p>
---	---