


CORNER RECORD

COUNTY OF Madera T. 7 R. 23 M.D.B. & MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



West 1/4 corner Section 23 7/23

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set Monument from Original Northeast Bearing Tree

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set Monument 2" I.D. Aluminum Pipe 25" Long with 3/4" Aluminum cap stamped L.S. 4298

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

TIES:

- N 20° E 28.7' 10" S. Pine
- N 84° E 42.9' 20" S. Pine
- S 70° W 36.15' 26" R. Fir
- N 70° E 33.0' Original Bearing Tree Stump/Scribing

All New Bearing Trees Blazed & Scribed

Copied from R/S by Jones L.S. 4298

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No.: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET YES NO