


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 7 SOUTH, RANGE 23 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



Northeast corner Section 24 7/23

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found Rock Mound & four Original Bearing Trees

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set mon. 2" Aluminum Pipe 25" Long with Aluminum Cap (3/4") Stamped L.S. 4298 in rebuilt Rock Mound

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

- S 76° W 37.0' "X" Marked in Bearing Tree Original
- S 56° E 25.0' Stump and old "K" Tag Original
- S 4° 30' E 22.0' New B.T. 10" Fir
- N 60° 45' E 11.0' New B.T. 10" Fir
- N 49° W 42.6' New B.T. 8" Fir

All other original B?T. are dead and down

All new Bearing Trees Blazed & Scribed

Copied from R/S BY Jones L.S. 4298

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
 STATEMENT ON BACK OF SHEET: YES NO