


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 7 SOUTH, RANGE 23 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



WEST 1/4 CORNER SECTION 24 7/23

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [X] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

SET BY SINGLE PROPORTION

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET MON. 2" ALUMINUM PIPE 25" LONG WITH 3/4" ALUMINUM CAP
CAP STAMPED L.S. 4298 IN ROCK MOUND

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

S 54° W 13.40' 14" FIR
S 12° E 16.80' 10" FIR
EAST 22.10' 20" FIR

all new bearing trees Blazed & Scribed

COPEd FROM R/S BY JONES L.S. 4298

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES [] NO []