CORNER RECORD

Brief Legal De	scription <u>Parcel</u>	2 of Parcel Map reco	rded in Bk 26 of Ma	City of Bass Lake County of Madera , C Brief Legal Description Parcel 2 of Parcel Map recorded in Bk 26 of Maps at Page 118, MCI				
		· · · · · · · · · · · · · · · · · · ·		aps at Page 118,	MCR			
		CORNER TYPE		COORDINATES (Optional)				
Section 25 T7S, R23E, MDM	Rancho		Zone NAD83 Epoch	NGVD29 Metric	NAD27 🗆 NAD8			
Corner -	Left as found □	Found and tagged 🛚	Established 🗀	Reestablished X	Rebuilt 🗆			
dentificatior stablish or r	n and type of co reestablish the	orner found: Eviden corner:	ce used to identi	fy or procedure	used to			
ound and acc	epted 3/4" iron p	pipes no tag, or monu	ments as noted.					
description	of the physical							
	ipe with plastic c	condition of the marked LS4633	onument as foun	ASOLAND	SUR			
et 3/4" iron p See sketch, Pa	ipe with plastic c		onument as foun	ROBIN RASMU	SUP. D. P. SSEN			
See sketch, Pa	survey Survey Act on	YOR'S STATEMENT	rmance with	D LAND	SUR ID. SSEN			
See sketch, Pa	SURVEN SURVEN Was prepared by me or Act onJanuary 12 COUNT Was received	YOR'S STATEMENT under my direction in confo	rmance with, 2012 13 TEMENT examined	ROBIN BASMU	SUR P SSEN P SSEN P SSEN P SSEN P SSEN P SSEN P SO SURVEYOR P			

