


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 7 SOUTH, RANGE 23 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19 _____



NORTH 1/4 CORNER SECTION 25 7/23

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [X] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

SET MONUMENT FROM ORIGINAL 54" FIR WITH BLAZE (SNAG)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET MON. 2" ALUMINUM PIPE 25" LONG WITH 3/4" ALUMINUM CAP STAMPED L.S. 4298

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____ ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

- N 6° E 22.20' 54" FIR (SNAG) ORIGINAL
N 42° E 44.00' 14" Y. PINE
S 52° E 33.40' 14" BLACK OAK
S 66° W 38.50' 20" FIR

ALL NEW BEARING TREES BLAZED & SCRIBED

COPIED FROM R/S BY JONES L.S. 4298

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19 _____

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED _____ 19 _____

BY: _____

TITLE: _____

DOCUMENT No: _____ STATEMENT ON BACK OF SHEET: YES [] NO []