


CORNER RECORD

CITY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT MAY 1989



N 1/4 Section 1 8/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 METHODS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(27) N 1/4 CORNER SECTION 1 8/19

FOUND A 2" IRON PIPE UP 11" WITH A BRASS CAP STAMPED FOR THE CORNER AND L.S. 4126, IN A 2' DIA. X 1/2' HIGH ROCK MOUND.

ORIGINAL BEARING TREES:

1. A 26.4" WHITE OAK WITH OPEN BLAZE AND VISIBLE AXE MARKS BEARS S.30 3/4° E. 48.2' ((S.32° E. 47.5'))
2. A 25.2" DIA. WHITE OAK WITH A HEALED BLAZE BEARS N.15 1/4° W. 27.4' ((N.15° W. 26.4'))

NEW TIES:

3. A 10.7" DIA. WHITE OAK, BEARS N.21 1/2° E. 27.13'
4. A 10.7" DIA. WHITE OAK, BEARS N.65° E. 17.53'
5. A 9.9" DIA. WHITE OAK, BEARS S.18 1/4° E. 74.98'

CORNER LIES ON A FENCELINE RUNNING N'LY AND S'LY AND 110' SOUTH OF THE CENTERLINE OF COUNTY ROAD 600.

SKETCH: (Include reference)

COPIED FROM R.S. BY SEIB-L.S. 5509 36/45-46

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET