


**CORNER RECORD**

COUNTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
 CORNER IDENTIFICATION - DATE OF VISIT April 1990



**SW SEC. 18/19**

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENT

*SOUTHWEST COR. SEC. 18/19  
 FD 1 1/2" I.P. TAGGED L.S. 2737 UP 2"  
 TIES:  
 1. A NAIL + TAG L.S. 5509 IN A ROCK 2' X 2 1/2' X 2'  
 HIGH, BEARS S. 15° 51' 36" E. 10.88'  
 2. FD. NAIL + TAG L.S. 2737 IN A ROCK 3' X 9' X 3'  
 HIGH, BEARS N 10° 16' 16" E. 28.22'  
 3. A CHISELED CROSS ON A ROCK, 1' X 2 1/2' HIGH,  
 BEARS S. 76° 47' 16" W. 70.37'  
 - THE COR. IS ON THE WEST SIDE OF THE EAST  
 GATE POST IN AN E/W FENCE.  
 - THE COR. LIES 535' EAST OF A GULCH*

CALIFORNIA COORDINATE SYSTEM  
 STATIONS USED: NGS (USC & GS)  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_

TION \_\_\_\_\_ STATION \_\_\_\_\_  
 EASTINGS (00) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

**COPIED FROM RS 42/28.29**

**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON \_\_\_\_\_ 19\_\_\_\_

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No. \_\_\_\_\_

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19\_\_\_\_  
 AND EXAMINED AND FILED \_\_\_\_\_ 19\_\_\_\_

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET

YES  NO