

CORNER RECORD

COUNTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT MAY 1989



N 1/4 SECTION 2 8/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

N 1/4 CORNER SECTION 2 8/19

FOUND A 1" IRON PIPE, UP 9", TAGGED L.S. 2737 IN A 2 1/2' DIA. X 1/2' HIGH ROCK MOUND.

SKETCH: (Include referen

ORIGINAL BEARING TREES

1. DOWN AND ROTTING PINE 2' DIA. BEARS N.14°W. 10.0' (N.12°W. 9.9')
2. PINE REMAINS BEARING N.57°E. 11.0' (N.57°E. 11.2')

NEW TIES

3. AN 11.8" DIA. WHITE OAK BEARS N. 2°W. 39.85'
4. A NAIL AND SHINER IN A 10' X 4' X 2' HIGH ROCK BEARS S.44°W. 42.61'

COPIED FROM R.S. BY SEIB-LS. 5509 36/45-46

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No.: _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET