


CORNER RECORD

COUNTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT MAY 1989



NE. COR. SECTION 2 8/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

26 NE CORNER SECTION 2 8/19

SKETCH: (Include referen

FOUND NO EVIDENCE OF THE ORIGINAL CORNER MONUMENT OR ACCESSORIES RE-ESTABLISHED THE CORNER POSITION BY SINGLE PROPORTIONATE MEASUREMENT. SET REBAR 1 CAP, UP 8". BUILT A 2' DIA. X 1/2' HIGH ROCK MOUND AROUND MONUMENT.

- NEW TIES:
- 1. AN 11" DIA. WHITE OAK BEARS S.73° E. 68.73'
 - 2. A 9" DIA. WHITE OAK BEARS S.86° W. 22.32'
 - 3. A 9" DIA. WHITE OAK BEARS N.7° W. 14.71'

CORNER LIES 37 1/2' EAST OF A FENCELINE RUNNING N'LY AND S'LY
FOUND A 4" X 4" X 5' HIGH POST IN A 2 1/2' DIA. ROAK MOUND S. 9 1/2 E. 71.6' FROM CORNER - NOT ACCEPTED. FOR SECTION CORNER

COPIED FROM R.S. BY SEIB-LS. 5509 36/45-46

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____
L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____
TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET