


CORNER RECORD

COUNTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT MAY 1989



SW cor. Section 2 8/19

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
METHODS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (M) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

(38) SW CORNER SECTION 2 8/19
FOUND 2" IRON PIPE WITH A 2" DIA. BRASS CAP, FLUSH, STAMPED FOR THE CORNER AND WITH L.S. 2737
FOUND 4 ORIGINAL BEARING TREES
CORNER LIES N.54°E. 7± FROM A FENCE CORNER, FROM WHICH FENCES RUN N'LY, W'LY AND E'LY

Copied from R.S. by SEIB-L.S. 5509 36/45-46

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON _____ 19____

SIGNED: _____
L.S. or R.C.E. No.: _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____
BY: _____
TITLE: _____

DOCUMENT No. _____
STATEMENT ON BACK OF SHEET