


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MADERA, California

Brief Legal Description NORTH 1/4 CORNER SECTION 3 8/19.



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

<p>A description of the physical condition</p>	<p><u>NORTH 1/4 CORNER SEC. 3 8/19</u>                  FOUND NO EVIDENCE OF ORIGINAL WITNESS CORNER OR ACCESSORIES. REESTABLISHED THE CORNER POSITION BY SINGLE PROPORTION. THE CORNER POSITION FALLS IN RIVER BED SET PEBBLE &amp; CAP L.S. 5509, UP 4" AS A WITNESS CORNER N. 71° 16' E. 64.72                  FROM THE TRUE CORNER POSITION!                  BUILT 1.5" DIA. ROCK AND AROUND MONUMENT TIES FROM WITNESS CORNER:                  1. A CHISELED CROSS IN A ROCK 6" x 10" x 4.5" HIGH                  S. 65° 32' 31" W. 57.46                  2. A CHISELED CROSS IN A ROCK 3" x 4" x 2" HIGH                  S. 22° 51' 07" W. 135.45                  3. A CHISELED CROSS IN A ROCK 6" x 12" x 3.5" HIGH                  S. 66° 05' 03" E. 200.68</p>	<p>as set or reset: _____</p>
--	---	-------------------------------

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment COPIED FROM RECORD OF SURVEY 42/121.  
SURVEYED BY JONES & SNYDER.