


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of MADERA, California

Brief Legal Description NORTHWEST CORNER SECTION 3 8/19



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

<p>A description of the physical</p>	<p><u>N.W. CORNER SEC. 3 8/19</u>                  FOUND NO EVIDENCE OF THE ORIGINAL CORNER OR ACCESSORIES.                  REESTABLISHED THE CORNER POSITION BY SINGLE PROPORTIONS.                  SET REBAR 4 CAP L.S. 5509, UP 6". BUILT 2.5" DIA. X 0.5" HIGH                  ROCK AND AROUND MONUMENT.                  FROM WHICH BEARS:                  1. A P.K. NAIL &amp; TAG L.S. 5509 IN A ROCK 2.5' x 3' x 2' HIGH                  N. 34° 54' 40" E. 74.69                  2. A P.K. NAIL &amp; TAG L.S. 5509 IN A ROCK 4' x 4' x 2' HIGH                  S. 37° 09' 41" E. 124.73                  3. A P.K. NAIL &amp; TAG L.S. 5509 IN A ROCK 2' x 4' x 1' HIGH                  S. 17° 43' 44" W. 65.02</p>	<p>reset: _____</p>
--------------------------------------	--	---------------------

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19\_\_\_\_.

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19\_\_\_\_ and examined and filed \_\_\_\_\_ 19\_\_\_\_.

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment COPIED FROM RECORD OF SURVEY 42/121.  
SURVEYED BY JONES & SNYDER