


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description SOUTH 1/4 CORNER SECTION 3 8/19



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SOUTH 1/4 CORNER
SECTION 3 8/19
 SET BY SINGLE PROPORTION
 PR. 1 1/2" I.P. IN A ROCK. NR. L.S. 2737
 N. 0°18'21"E. 143.38' - NOT ACCEPTED
 TIES:

A description of the ph

- 1.) A NAIL & TAG L.S. 5509 IN A 4 1/2" X 1 1/2" X 2" HIGH ROCK MD. BEARS N. 64° 21' 00" E. 31.21'
 - 2.) A MAIN TRUNK OF A 16" DIA. FORKED LIVE OAK, BEARS S. 51° W. 10.84'
 - 3.) A NAIL & TAG IN A 4 X 2 X 1 1/2" HIGH ROCK BEARS N. 22° 27' 12" W. 42.11'
- THE CORNER LIES 66' SOUTH OF AN E/W FENCELINE, & 200' WEST OF WILLOW CREEK.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment COPIED FROM PARCEL MAP # 2929
SURVEYED BY JONES & SNYDER