


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description NORTH 1/4 CORNER SECTION 4 8/19.



CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

A description of the physical corner

NORTH 1/4 CORNER SEC. 4 8/19
 FOUND 8"x9"x12" STONE UPRIGHT IN THE CENTER OF A
 2' DIA. x 0.5' HIGH ROCK NO. - REPLACED STONE WITH
 REBAR & CAP L.S. 5509, 1" T"
 FROM WHICH BEARS:

1. A 12" WHITE OAK N. 20°W. 56.00 - FOUND ORIGINAL SCRIBING
 3" DEEP <N. 4°W. 53.46
2. A NAIL & TAG L.S. 5509 IN A ROCK 1"x3"x1" HIGH
 S. 35°40' 03"E. 41.72
3. A NAIL & TAG L.S. 5509 IN A ROCK 2.5'x5'x2" HIGH
 N. 60°52'35"W. 31.57
4. A NAIL & TAG L.S. 5509 IN A ROCK 2.5'x3.5'x1" HIGH
 S. 65°59'36"W. 43.01

reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined
 and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment COPIED FROM RECORD OF SURVEY 42/121.
SURVEYED BY JONES & SNYDER