


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MADERA, California

Brief Legal Description NORTHWEST CORNER SECTION 4 8/19



### CORNER TYPE

- Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

TIES:  
THE CORNER LIES 205 FT. WEST OF A GULCH  
THE CORNER LIES N 9 1/2° E 240 FT FROM A FENCE CORNER N-S-W  
THE CORNER LIES 48 FT. NORTH OF AN E/W FENCE.

A description of the physical condition of the monument as found and as set or reset: FOUND A 4" DIA X 2'

HIGH ROCK MD SET NAIL & TAG L.S. 5509 IN CENTER FROM WHICH BEARS:

1. A PK NAIL & TAG L.S. 5509 IN A ROCK 3'X5'X5' HIGH S10°W 21.04.
2. A PK NAIL & TAG L.S. 5509 IN A ROCK 3'X4'X2.5' HIGH N66°W. 23.53.
3. A PK NAIL & TAG L.S. 5509 IN A ROCK 2 1/2'X2 1/2'X1' HIGH N71°E 2.87.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment COPIED FROM RECORD OF SURVEY 42/121

SURVEYED BY JONES & SNYDER