| CORNER RECORD | Document Nur | nber | |
|--|---|--|----------------------------|
| City of | | | ———, California |
| Brief Legal Description SOUTH 14 CORNER | SECTION 4 | 8/19 | |
| Government Corner Meander Rancho Date of Survey | Contrôl [] Property [] | . (0 N E Zone | ORDINATES Optional) Datum |
| Corner — Left as found Found and tagged | ☐ Established ☐ | Reestablished [V | Rebuilt [|
| FOUND NO EVIDENCE OF ORIGINAL CO THE CORNER BY SINGLE PROPORTION 4". BULT ROCK MD 2 DIA ARDUND L. A P.K. NAIL & TAG L.S. 5509, S71°37'29" E. 22.42 A description of the physical condition of the monument 2. A P.K. NAIL & TAG L.S. 5509 S. NG° 15'16" W. 53.64. | N. SET REBAMONUMENT. F IN A ROCK 4' as found and as set of IN A ROCK. | R & CAP L.S FRDM WHICH B XT'X3' HIGH reset: 3'XT'X2' HIG | 5509, IJP EARS: tl |
| 3. A P.K. NAIL & TAG L.S. 5 N. 75°07'02" W. 101.83. | 509, IN A F | ROCK 5'X8'X | 2.5' HigH |
| SURVEYOR'S STATEMENT | г | | |
| This Corner Record was prepared by me or under my | direction in conforma | nce with | `. |
| the Land Surveyors' Act on | 19 | | |
| Signed L.S. or R.C.E. | • | | |
| COUNTY SURVEYOR'S STATE | MENT | | |
| This Corner Record was received | 19 and e | xamined | e. |
| and filed 19 | | | |
| Signed | Title | | • |
| County Surveyor's Comment COPIED FROM SURVEYED BY | RECORD OF JONES & S | SURVEY 4 | 7/121 |
| | | | |
| | | | |