


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description WEST 1/4 CORNER SECTION 4 8/19.



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SET REBAR & CAP L.S. 5509, UP 4", AT INTERSECTION OF RECORDED DISTANCES FROM ORIGINAL BEARING TREES - BUILT A ROCK MD. 2' DIAM X 0.5' HIGH AROUND MONUMENT FROM WHICH BEARS:

1. A 17" WHITE OAK N. 51° E 23.76 - FOUND ORIGINAL SCRIBING 4" DEEP
< N 76 1/2° E 23.76 >

A description of the physical condition of the monument as found and as set or reset:

- 2. A 2 1/2" WHITE OAK N. 4 3/4° W. 85.80 ORIG < N. 5° W 85.80 >.
- 3. CHISELED CROSS IN A ROCK 1' X 2' X 0.5' HIGH S. 39° 57' 40" E 20.94.
- 4. A CHISELED CROSS IN A ROCK 1' X 4' X 2' HIGH S. 22° 39' 00" W 49.33.
- 5. A PK NAIL & TAG L.S. 5509 IN A ROCK 4' X 5' X 2' HIGH
N 66° 14' 10" W. 21.71.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____.

Signed _____ Title _____

County Surveyor's Comment COPIED FROM RECORD OF SURVEY 12/121
SURVEYED BY JONES & SNYDER.