


CORNER RECORD

COUNTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT 2-6 1990



E 1/4 8 8/19

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT

E 1/4 COR. SEC. 8, 8/19.
FD. NO EVIDENCE OF THE ORIGINAL CORNER MONUMENTS OR ACCESSORIES.
SET REBAR & CAP UP 4" AT THE SINGLE PROPORTIONATE POSITION. BUILT
A ROCK AROUND 1 1/2" DIA. X 1/2" HIGH AROUND MONUMENT.
TIES:
1. A NAIL & TAG L.S. 5509 IN A ROCK 4'X2'X2' HIGH S. 71 1/2° W. 178.67.
2. A NAIL & TAG L.S. 5509 IN A ROCK 7'X4'X2' HIGH N. 17° E. 51.36.
3. A NAIL & TAG L.S. 5509 IN A ROCK 10'X4'X2 1/2' HIGH S. 50° E. 123.00.
- THE CORNER LIES S. 71° W. 27.3' FROM A FENCE CORNER FROM
WHICH FENCES RUN N'LY, S'LY, & W'LY.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (E) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS 42/120

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____ TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET YES NO