


CORNER RECORD

COUNTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT 2-6 1990



N 1/4 8 8/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

N. 0° 26' 27" W. 26.33.17
N. 1/4 COR. SEC. 8, 8/19,
 FOUND NO EVIDENCE OF ORIGINAL CORNER MONUMENT.
 REESTABLISHED CORNER POSITION AT INTERSECTION OF
 RECORD DISTANCES FROM FOUND ORIGINAL BEARING
 TREES, SET REBAR & CAP, UP 4". BUILT A 1 1/2" DIA. X
 1/2" HIGH ROCK MOUND AROUND MONUMENT.
 TIES:
 1. A WHITE OAK, 20" DIA., BEARS 6.9° W. 84.48' (6.4 1/2° W. 84.48) ORIG.
 FOUND SCRIBING 4" DEEP.
 2. A WHITE OAK 25" DIA., BEARS: N. 35° E. 13.20' (N. 41 1/2° E. 13.20') ORIG.
 3. A NAIL & TAG L.S. 5509 IN A ROCK 7"x 5 1/2" X 2" HIGH BEARS: N. 67 1/2° W.
 59.23'.
 4. A NAIL & TAG L.S. 5509 IN A ROCK 7"x 3" HIGH BEARS: N. 12° W. 52.88.
 5. A NAIL & TAG L.S. 5509 IN A ROCK 4 1/2" X 3 1/2" HIGH BEARS: N. 83 1/2° E. 55.99.
 - THE CORNER LIES 5.27 3/4° E. 11.4' FROM A FENCE CORNER FROM WHICH
 FENCES RUN N'LY, S'LY, & W'LY.

PHYSICAL DESCRIPTION OF MONUMENTS REESTABLISHED

CALIFORNIA COORDINATE SYSTEM ORDER:

STATIONS USED: NGS (USC & GS)
 ZONE _____ ELEVATION _____

STATION _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS 42/120

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO