


CORNER RECORD

COUNTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT 2-6 1990



~~8 8/19~~
SW

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

N.W. COR. SEC. 17, 8/19,
FD. NAIL 1/2" BELOW PAVEMENT, REMONUMENTED WITH REBAR & CAP
DOWN 1/2"

PHYSICAL DESCRIPTION OF MONUMENTS RE

- TIES:
1. AN OAK STUMP WITH ROTTED BLAZE BEARS S.15°W. 125.7' (S.15°W. 124.08) ORIG
 2. A ROTTEN OAK STUMP BEARS N.41°W. 45.2' (N.41°W. 44.22) ORIG.
 3. FD. NAIL & SHINER IN SOUTH SIDE OF FENCE POST BEARS S.84°W. 21.36'
 4. FD. NAIL & SHINER IN SOUTH SIDE OF A TELEPHONE POLE BEARS N.77°E. 13.88'
 5. A NAIL & TAG L.S. 5509 IN A ROCK 5'x4'x2 1/2' HIGH BEARS N.20°W. 93.95'
- THE CORNER LIES 6' EAST OF THE CENTERLINE OF COUNTY ROAD # 613.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS 42/120

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____
L.S. or R.C.E. No.: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____
TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET YES NO