


CORNER RECORD

NTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT 2-6 1990



W 1/4 8 8/19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENT

W 1/4 COR SEC 8, 8/19
N. 0° 23' 04" W 2657.85'
 FD. NO EVIDENCE OF ORIGINAL CORNER OR ITS ACCESSORIES,
 SET REBAR & CAP UP 3" AT SINGLE PROPORTIONATE POSITION.
 BUILT A ROCK MOUND 2" DIA. x 1/2" HIGH AROUND MONUMENT.
 TIES:
 1. A NAIL & TAG L.S. 5509 IN A ROCK 6 1/2" x 3 1/2" x 2 1/2" BEARS S. 79° 34' W. 119.91'
 2. A NAIL & TAG L.S. 5509 IN A ROCK 4" x 3" x 2 1/2" BEARS N. 14° 34' W. 168.56'
 3. A NAIL & TAG L.S. 5509 IN A ROCK 2 1/2" x 1" x 1/2" BEARS S. 23° E. 94.90'
 — THE CORNER LIES 17 1/2' EAST OF THE CENTERLINE OF COUNTY ROAD # 613

IFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS 42/120

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____
 L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____
 TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET YES NO