


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description CENTER 1/4 CORNER SEC. 11 T8S, R19E



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|--------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |
| Date of Survey | _____ | | |

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

A description of the physical condition of the monument as found and as set or reset: _____

CENTER 1/4 CORNER SECTION 11 8/19 SET 5/8" REBAR L.S. 4298 IN ROCK MD.
 FROM WHICH BEARS:
 1) A 16" W. OAK (100%) N. 22° E. 81.92
 2) A 12" W. OAK N. 48° W. 72.50

COPIED FROM
RS 47/39

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment _____

