


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description EAST 1/4 CORNER SEC 11 T8S R19E



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

EAST 1/4 CORNER SECTION 11 1/4 19 SET 5/8" REBAR L.S. 4298 IN ROCK MID. AT SPLIT PDS. 12.5 SOUTH OF & DRAINAGE
AND 38.0 EAST OF & OF DRAINAGE
FROM WHICH BEARS:
 1) A 6" L. OAK CLUSTER (5) N. 34° E. 20.0 BLAZED
 2) AN 11" L. OAK S. 60° E. 29.5 BLAZED
 3) & CO. RD. # 612 EAST 98.5

COPIED FROM
RS 47/39

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on _____ 19____.
 Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19____ and examined
 and filed _____ 19____.
 Signed _____ Title _____

County Surveyor's Comment _____

