


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description SOUTH 1/4 CORNER SEC. 11 T8S, R19E



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SOUTH 1/4 CORNER SECTION 11 1/19 PD. ORIGINAL SET STONE IN ROCK MD. 1/4 S.W. BY
FROM WHICH BEARS:
 1) 16" W. OAK 5.66° N. 48.7 (ORIG.)
 2) 11" W. OAK 5.25° N. 39.0
 3) 11" W. OAK 5.66° E. 32.3

COPIED FROM
RS 47/39

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____.

Signed _____ Title _____

County Surveyor's Comment _____