


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of \_\_\_\_\_, California

Brief Legal Description SOUTHEAST CORNER SEC 11 T8S, R19E



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SOUTHEAST CORNER SECTION 11 9/19  
FD. ORIGINAL SET STONE IN OLD REMAINS OF E. N. FELICE & NW B.T. (ORIG.)  
FROM WHICH BEARS:  
 1) A 19" W. OAK N. 85° W. 78.0 (ORIG.) BT  
 2) A 14" L. OAK N. 28° W. 13.43 1 BLAZED  
 3) A 4" W. OAK N. 64° W. 60.4 1 BLAZED  
 4) 50" REBAR L.S. 4296 N. 146° 06' W. 0.59 N.C. ON N/S OF STONE  
 5) 1/2" IRON PIPE L.S. 4290 S. 88° 51' 25" E. 181.24 NOT ACCEPTED

COPIED FROM  
RS 47/39

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_.

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_