


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description SOUTHWEST CORNER SEC. 11 T8S, R19E



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|--------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |
| Date of Survey | _____ | | |

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

_____ SOUTHWEST CORNER SECTION 11 8/19 10.1 P. IN ROCK N.D.
_____ FROM WHICH BEARS:
_____ 1.) A 16" L. OAK N. 25° E. 18.48 (ORIG.) B.T. DEAD WITH SCRIBING
_____ 2.) A 40" W. OAK S. 18° 11' 34" E. 93.72 (ORIG.) B.T. WITH HIGH BLAZE
_____ 3.) A NAIL IN ROCK N. 46° 50' 22" E. 11.94
_____ 4.) A NAIL IN ROCK S. 51° 17' 58" E. 11.72

COPIED FROM
RS 47/39

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____.

Signed _____ Title _____

County Surveyor's Comment _____