


CORNER RECORD

Document Number _____

City of _____ County of _____, California

Brief Legal Description WEST 1/4 CORNER SEC 11 T8S, R19E



CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

WEST 1/4 CORNER SEC 11 T8S, R19E FOUND TWO ORIGINAL GOV'T. BEARING TREES (CUT INTO ONE TO EXPOSE SCRIBING)
 FROM WHICH I REPLACED CORNER WITH A 5/8" REBAR IN REMAINS OF ROCK NO. 8.0 EAST OF N-S FENCE AND 4.75 NORTH OF E-W FENCE
 FROM WHICH BEARS:

- | | | | |
|------------------------|-------------------|-------|-------------------------------------|
| 1) A 21" N. OAK | N. 42° E. | 91.3 | 1 BLAZED |
| 2) 2 1/2" N. OAK CL. | N. 17° 42' 40" W. | 41.80 | 1 BLAZED |
| 3) A N. OAK | S. 10° 21' 14" W. | 60.45 | 1 BLAZED |
| 4) A 34" W. OAK | S. 87° E. | 70.40 | (DRIG.) CUT INTO AND FOUND SCRIBING |
| 5) 1 1/2" N. OAK STUMP | N. 60° W. | 11.19 | (DRIG.) |

set _____

 COPIED FROM
 RS 47/39

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19____.

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19____ and examined and filed _____ 19____.

Signed _____ Title _____

County Surveyor's Comment _____

