


**CORNER RECORD**

COUNTY OF MADERA    TOWNSHIP    **8**    SOUTH,    RANGE    **19**    EAST,    M.D.B.&M.    CALIFORNIA

CORNER TYPE:    GOV'T. CORNER     MEANDER     RANCHO     CONTROL     OTHER

CORNER IDENTIFICATION - DATE OF VISIT:    MARCH    19 77



**NORTHWEST CORNER OF SECTION 16, 8/19.**

CORNER - LEFT AS FOUND     FOUND AND TAGGED     REESTABLISHED OBLITERATED CORNER     REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

**Found 1 1/4" Iron Pipe in fence line North & South.**

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

**set 3/4" Iron Pipe in found 1 1/4" Iron Pipe (old).**

CALIFORNIA COORDINATE SYSTEM ORDER:    FIRST     SECOND     THIRD

STATIONS USED:    NGS (USC & GS)     STATE     COUNTY     OTHER     STATION \_\_\_\_\_ STATION \_\_\_\_\_

ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

**TIES**

**14.5 feet NORTH of fence corner junction North & EAST.**

**61.7 feet N.E. of an 18" White Oak.**

**56.0 feet EAST of a 36" White Oak.**

**47.0 feet S.E. of LS tag in rock.**

**Copied from Parcel Map 1237  
Surveyed by Stephen L. Jones, L.S. 4298**

**24/13**

**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

\_\_\_\_\_ 19 \_\_\_\_.

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No: \_\_\_\_\_

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19 \_\_\_\_

AND EXAMINED AND FILED \_\_\_\_\_ 19 \_\_\_\_.

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No: \_\_\_\_\_  
STATEMENT ON BACK OF SHEET:    YES     NO